	Property Evaluation	Benchmark
Building Interior		
Room By Room Inspection	$\checkmark$	$\checkmark$
Electrical	$\checkmark$	$\checkmark$
Walls	$\checkmark$	$\checkmark$
Ceiling	$\checkmark$	$\checkmark$
Plumbing	$\checkmark$	$\checkmark$
Hazardous Materials	$\checkmark$	$\checkmark$
HVAC Operation	$\checkmark$	$\checkmark$
Window Operation	$\checkmark$	$\checkmark$
Door Operation	$\checkmark$	$\checkmark$
Flooring/ Floor coverings	$\checkmark$	$\checkmark$
Restrooms	$\checkmark$	$\checkmark$
Corridors	$\checkmark$	$\checkmark$
Building Exterior		
Gates and Fences	$\checkmark$	$\checkmark$
Roof	$\checkmark$	$\checkmark$
Gutters	$\checkmark$	$\checkmark$
Exterior Wood	$\checkmark$	$\checkmark$
Exterior Paint	$\checkmark$	$\checkmark$
Exterior Stucco	$\checkmark$	$\checkmark$
Window fit & function	$\checkmark$	$\checkmark$
Door fit and function	$\checkmark$	$\checkmark$
Decking	$\checkmark$	$\checkmark$
Attached closets/ rooms	$\checkmark$	$\checkmark$
Landscaping	Limited	$\checkmark$
Grounds	Limited	$\checkmark$
Parking Lot	Limited	$\checkmark$
Report		
Report Summary	$\checkmark$	$\checkmark$
Digital copy of Report	$\checkmark$	$\checkmark$
Hardcopies of report	1 copy	2 copies
Room by Room description	$\checkmark$	$\checkmark$
Photographs	B&W	Color
Time for Action	$\checkmark$	$\checkmark$
Set Priorities		$\checkmark$
Repairs Priority Report/Matrix		$\checkmark$
Repair/ maintenance cost projection		$\checkmark$
Inspections Report		$\checkmark$
Maintenance Guidelines	General	Specific
Follow up evaluation (2 to 3 years later)		$\checkmark$
as requested by customer		v



Matthew Boomhower, President 858-395-8657 / www.southerncrosspc.com / matthew@southerncrosspc.com